


C2-2x55 Firmware v580

Released by Bruce Meldrum

18th August 2021

This firmware is for:

- Hardware: C2-2855, C2-2755 and C2-2655 only.
- Associated PC control software for applying the update: CORIOcontrol v1.2.11.0



Downloads

Download the latest firmware and CORIOcontrol here: tvone.com/firmware-updates

Release Details

More details about this release, and previous releases can be found here; https://tvone.com/tech-support/firmware/182-c2-2855-c2-2755-and-c2-2655-productsupport-and-firmware-updates

Installation instructions

Make sure you have CORIOcontrol software v1.2.11.0 or above installed.

If you cancel an update during installation, your unit is left in an unusable state. To recover, turn your device off and on, and run the firmware update procedure again.

All settings except the IP address are lost during a firmware update, including stills, logos and presets.

- 1. Open the CORIOcontrol software.
- 2. Use Ethernet or RS-232 to connect to your C2 unit.
- 3. Select System > Update Firmware > Pick Update file to use.
- 4. Navigate to and select the new firmware file you have saved on your PC.
- 5. Select Open.
- 6. Select **Start Update**.

When the update is complete, the unit restarts automatically and the CORIOcontrol software reconnects.

Contact us

www.tvone.com

tvONE NCSA

North, Central and South America

Sales: sales@tvone.com Support: tech.usa@tvone.com tvONE EMEA

Europe, Middle East, Africa and Asia Pacific

Sales: sales.europe@tvone.com Support: tech.europe@tvone.com



October 2017 C2-2x55 Firmware v580

Released by Bruce Meldrum

18th August 2021

Fixed

Due to component obsolescence issues, we have needed to release a new version
of firmware to deal with a component change. There is no change to the unit
behaviour.

Notes

- This firmware is functionally identical to firmware v579. **There is no user** benefit to upgrading units in the field.
- There is a known compatibility issue with LM1750HD when using analog RGB output (PC input on display).
- A Left-Push transition might show a corrupt top line.
- Some menus on the unit display do not flash when they are in edit mode.