

CORIOmatrix™ firmware M405_02

12/12/18

Released by Neil Baptiste

This software is for:

- Hardware: CORIOmatrix™ and CORIOmatrix mini™
- Firmware: Use CORIOdiscover™ v1.5.2.2 or later to update to this version

Downloads

Download the latest firmware here: tvone.com/firmware-updates

Download the latest CORIOdiscover software here:
tvone.crmdesk.com/answer.aspx?aid=21697

Previous releases

Read details on previous releases here:

tvone.crmdesk.com/image.aspx?mode=file&id=14919

Contact us

www.tvone.com

tvONE NCSA
North, Central and South America

✉ Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA
Europe, Middle East, Africa and Asia Pacific

✉ Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com

CORIOmatrix™ firmware M405_02

12/12/18

New

- NONE

Fixed

- System locks up when source switching is set to **freeze and cut**, and an attempt is made to remove any route made.

Notes

- Immediately after upgrading, your browser user interface might not be displayed correctly after logging in. Press Ctrl-F5 to fix this.
- When you first route a signal to an SDI or DVI output through the web interface, you may see a black output. To resolve this, change the routing to another input and back again.
- If you reboot the device through the web browser you might see an error message displayed saying "Failed to restart device", depending on your system configuration. This is usually caused by the browser timing out before the web interface has restarted. Wait 30 seconds, and press F5 to refresh your browser. You will then be able to continue as normal. Note that the same can happen if the system is rebooted as part of the Restore from SD option, or changing the network settings.
- The browser user interface lets you create more than 49 presets, however this is not actually supported. When you appear to be editing a preset number greater than 48, you are actually editing preset 48.