

The all NEW CORIOmaster2 (CM2 547)

Firmware M500_04

Released 10-08-20 By: Neil Baptiste

This software is for:

- Hardware: CORIOmaster2 (CM2-547).
 - Firmware: M500 or later, use CORIOdiscover™ v1.7.2.3 or later to update to this version
 - Control Software: CORIOgrapher v3.0.2.7 or later
- ✔ For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

Downloads

Download the latest firmware here: <http://www.tvone.com/firmware-updates>

Download the latest control software here:

- CORIOgrapher: <https://tvone.com/tech-support/software>
- CORIOdiscover <https://tvone.com/tech-support/software>

Previous releases

- M500_00

Contact us

www.tvone.com

tvONE NCSA
North, Central and South America

✉ Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA
Europe, Middle East, Africa and Asia Pacific

✉ Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com

The all NEW CORIOmaster2 (CM2 547)

Firmware M500_04

Released 10-08-20 By: Neil Baptiste

New Features

- System bandwidth 752 Gb
- 12 Gigapixel canvas space
- Window allocation now up to 64 Windows per canvas up to 128 windows per system
- Output allocation now up to 56 FHD Displays
- Input allocation up to 32 FHD sources
- Embedded and de-embedded audio support

Fixed

- REST API Windows values do not update until CLI read.
- Network time can now be set.

Known Issues

- User is able to select all resolutions on AVIP (Media card) channel 2, only 1080p60 is supported.
- Sending settings from CORIOgrapher 3.0 Target slows down over time if the console window is open.
- If HDCP is ON the input, and HDCP is NOT ON the output you will get a blank black picture, but the audio is present.
- FW update failed (AVIP media card) (**Workaround**, is send this command via console "**CORIOmax.MediaCard_Update(force)**")
- The REST API does not yet allow layouts to be set up. This will need to be done using CORIOgrapher.